























WASHING

-  40 °C colored wash
-  40 °C mild process
-  40 °C very mild process
-  Cold
30°C or 85°F
-  Warm
40°C or 105°F
-  Warm / Hot
50°C or 120°F
-  Wash by hand
-  Do not wash





BLEACHING

-  Any bleaching agent allowed
-  Only oxygen / non- chlorine bleach allowed
-  Do not bleach










DRYING

-  Tumble drying possible
normal temperature 80 °C
-  Tumble drying possible
lower temperature 60 °C
-  Do not tumble dry
-  Line drying
-  Drip line drying
-  Flat drying
-  Drip flat drying
-  Line drying in the shade
-  Drip line drying in the shade
-  Flat drying in the shade
-  Drip flat drying in the shade

IRONING

-  Iron at maximum soleplate temperature (200 °C)
-  Iron at maximum soleplate temperature (150 °C)
-  Iron at maximum soleplate temperature (110 °C)
without steam
-  Do not iron

PROFESSIONAL TEXTILE CARE

-  Professional dry cleaning with perchloroethylene
and hydrocarbons normal process
-  Professional dry cleaning with perchloroethylene
and hydrocarbons mild process
-  Professional dry cleaning with hydrocarbons
normal process
-  Professional dry cleaning with hydrocarbons
mild process
-  Do not dry clean
-  Professional wet cleaning normal process
-  Professional wet cleaning
-  Professional wet cleaning very mild process
-  Do not wet clean

